

Q40

Mechanical parts procured under this order are subject to sample inspection for dimensional features per SPAR-RMS-PA.1948.

Q41

Government Source Inspection is required prior to shipment of item(s). Seller shall provide objective evidence of Government Source Inspection with shipment of item(s).

Q42 NO ZINC OR CADMIUM

Seller shall not use any zinc or cadmium processes, part(s), or assemblies on the items supplied on this procurement.

Q43 Deleted

Q45 Deleted

Q47 DELEGATED INSPECTION AUTHORITY

Seller assigns a source acceptance delegate, who assumes full responsibility for all aspects of part conformity. The delegate signs statement, "This shipment accepted by Novatronics Supplier Quality Assurance Delegate."

Q49 First Article Inspection Required

The seller shall provide a first article inspection report with the shipment if required. First article inspection is required, as a minimum, under the following conditions:

- The first lot furnished to Novatronics.
- changes to the products configuration.
- two years or more between shipments

For first article format ref AS9102

Note: if item supplied is a catalog item a previously completed First Article Inspection report may be supplied. Material Certifications to be supplied with first article.

Q50 Drawing Interpretation

Unless otherwise stated by the drawing (Drawing notes take precedence) the following requirements must be maintained:

1:"Remove burrs and break sharp edges" this shall be interpreted as no burrs are acceptable and the edges shall be broken .005" max.

2:"Maintain sharp corner" this shall be interpreted as absolutely no burrs are acceptable and corners shall be marred or broken no more than .002" max.

- the packaging is labelled to indicate that it contains electrostatic sensitive parts.

Q51 DEBURR PROCESS

The seller shall deburr parts as per Novatronics Deburring Procedure, QUALITY STD #7.

Q52 NADCAP Approved Sources for Special Processes

Special processes performed on this item must be performed by a NADCAP approved source.

Q53 Traceability to Source of Origin Required

The seller must ensure that all items on this procurement are traceable to source of origin by, as applicable: lot, date code(s) and batch numbers(s) A traceability number must be recorded on all release documentation submitted to Novatronics.

Q54 Boeing Approved Suppliers Only

Any special process's called out on drawing may only be performed by processors listed on the approved supplier listing D1-4426 for this process..

Q55 Traceability

Certificate of conformance for Raw materials and/or supplies relative to this order shall be supplied with each shipment.

Q56 Novatronics Delegated Inspection Authority

Novatronics assigns a delegated inspection source who is responsible for ensuring parts meet all specified requirements.

Q57 SHIPMENT INFORMATION FOR RAW MATERIAL

All raw material purchased by Novatronics' must be shipped to: PINNACLE c/o CWC
193 Lorne Avenue West, Stratford, Ontario N5A 6S4

Q58 NOVATRONICS DELEGATED INSPECTION AUTHORITY

only applies to this product when manufactured by Aero-Safe Technologies Inc.

Q59 NOVATRONICS DELEGATED INSPECTION AUTHORITY

only applies to this product when manufactured by Ed & Son

Q80 REPAIRS

-Repairs of material or parts damage or found defective during fabrication, is not permitted when such repairs deviate from the specified requirements of the purchase order, material, product design, process or specification unless authorized by Novatronics in writing.